Teco Drive & Motor Wiring Diagram – Apollo III (Example)



R, S, T Fuses			
Single Phase		Three Phase	
Drive	Fuse (A)	Drive	Fuse (A)
20C	8	20C	6
30C	10	30C	8
50D	-	50D	16
75D	-	75D	20

r, s Fuses	
Drive	Fuse (A)
20C	10
30C	10
50D	10
75D	10