


ELECTRICAL ENCLOSURE WIRING DIAGRAM

APOLLO III (EXAMPLE)

Inputs		
Signal	Port/Pin	Function
X0	11-0	Drive Fault
X1	11-1	
X2	11-2	
X3	11-3	
X4	11-4	
X5	11-5	
X6	11-6	
X7	11-7	
X8	11-8	
X9	11-9	
X10	11-10	
X11	11-11	
X12	11-12	
X13	11-13	
X14	11-14	
X15	11-15	

Outputs				
Relay	Port/Pin	Function	On	Off
R1	11-0	Enable		
R2	11-1	Mist	M7	M9
R3	11-2	Coolant	M8	M9
R4	11-3		M200	M201
R5	11-4		M202	M203
R6	11-5		M204	M205
R7	11-6		M206	M207
R8	11-7		M208	M209



Ground & Neutral

Three Phase Power